Y S ENGINEERING Mfg of : Dies, Hydraulic Fixtures, All Machine Maintenance, Other Comp. of Dies

Add : Plot No.17, Gut No.71, Wadgaon(Ko), MIDC Waluj, Aurangabad-431136. Email : ysengineering@rediffmail.com, Mob : 9552366855

Ref No :

Date : 28/2/2024

METHOD STATEMENT FOR FABRICATION WORK

• . *•

Α				
Job Description Repair of		nd machine r	nodification a	and all types of maintenance
Area/ Locatio Plant-	in :			taken perera repri ina birnaria
Aux Permit Type :		General work, mechanical work		
B				
Major hazard	s associated with the	job:		
1	Electric Shock	Linarici Actavi	5	
2	Fire and Explosion Slip, Trip and Fall Hazard			
3				
4	Falling Object			
What Worst c	an Hannen?			
1	Fatality or permane	ent disability du	e to Electric Shoc	k, etc
С				
PPE's Require	d for Jobs: Safety Sho	es. Safety Glass	es. Hand Gloves.	Welding apron
				Il machine läthe machine, grinding machine
***************************************			machine and	
Activities sequ	uences: (What , who	White the second state of	na na katala na katal	
Sr. no	Activity	Who Will do	Risk Involved	Risk Mitigation/Control Measure
1	Take Work Permit	Executor will take the permit signed by	Nil	Full Compliance to PTW Process
5956	Instroctions/Note:	respective authorities		

(DIRECTOR) YOGESH SOMGIR **Y S ENGINEERING** Mfg of : Dies, Hydraulic Fixtures, All Machine Maintenance, Other Comp. of Dies

Add : Plot No.17, Gut No.71, Wadgaon(Ko),MIDC Waluj,Aurangabad-431136. Email : ysengineering@rediffmail.com, Mob : 9552366855

Ref No :

2	Provide the training for the persons who will work Fabrication activity.	SHE Officer/ Site Engineer Area Owner, Shift In Charge	Nil	Training to cover all the associated risks and job detail/method, PPE usage training, tool box talk shall be taken before start the acitivity. Only experince persons would e selected for the job.
3	Assessment of the work area before job starting	Area Owner	Slip trip Fall etc.	Assessment of the job area to ensure area must ne cleaned for work
4	Take all the hand tools and equipments required for perform work at site	Approved Contractor	Trip hazard due to improper handling Equipments and machines.	Ensure that the m/c machine are properly carried.
5	Start the Programming work grinding/drilling if required	Trained and experinced persons from contractors	As per attached hazards categories	Ensure that all work must be done by train person. Hand Gloves, safety goggles, must be required.
6	Removal of scraped material after work completion.	Contract Employees	Waste Cables	safety shoes, cotton hand gloves
7	Closing of Permit	Permit Executor and contractor	Violation of Permit	The permit should be handed over after getting it signed from Executor.
	4			

- 1 Get the permit to work along with height work permit from authorized person
- 2 Follow all the work instruction's strictly as per work permit
- 3 The switch board used must have ELCB
- 4 No cable Joints in portable electric equipment is acceptable.
- 5 Close Supervision while performing the work.



(DIRECTOR) YOGESH SOMGIR