

Y S ENGINEERING

Mfg of : Dies, Hydraulic Fixtures, All Machine Maintenance, Other Comp. of Dies

Add : Plot No.17, Gut No.71, Wadgaon(Ko),MIDC Waluj,Aurangabad-431136.

Email : ysengineering@rediffmail.com, Mob : 9552366855

Ref No :

Date : 28/2/2024

METHOD STATEMENT

A				
Job Description : Repair of machine spare and machine modification and all types of maintenance				
Area/ Location : Plant-				
Aux Permit Type :		General work, mechanical work		
B				
Major hazards associated with the job:				
1	Electric Shock		5	
2	Fire and Explosion			
3	Slip, Trip and Fall Hazard			
4	Falling Object			
What Worst can Happen?				
1	Fatality or permanent disability due to Electric Shock , etc			
C				
PPE's Required for Jobs: Safety Shoes, Safety Glasses, Hand Gloves, Welding apron				
Resources/ Tools Required for the Job : Electrical Tools grinder, Drill machine lathe machine, grinding machine milling machine and CMC				
Activities sequences: (What , who & How?)				
Sr. no	Activity	Who Will do	Risk Involved	Risk Mitigation/Control Measure
1	Take Work Permit	Executor will take the permit signed by respective authorities	Nil	Full Compliance to PTW Process



(DIRECTOR)
YOGESH SOMGIR

Y S ENGINEERING

Mfg of : Dies, Hydraulic Fixtures, All Machine Maintenance, Other Comp. of Dies

Add : Plot No.17, Gut No.71, Wadgaon(Ko),MIDC Waluj,Aurangabad-431136.

Email : ysengineering@rediffmail.com, Mob : 9552366855

Ref No :

2	Provide the training for the persons who will work Fabrication activity.	SHE Officer/ Site Engineer Area Owner, Shift In Charge	Nil	Training to cover all the associated risks and job detail/method, PPE usage training, tool box talk shall be taken before start the activity. Only experince persons would e selected for the job.
3	Assessment of the work area before job starting	Area Owner	Slip trip Fall etc.	Assessment of the job area to ensure area must ne cleaned for work
4	Take all the hand tools and equipments required for perform work at site	Approved Contractor	Trip hazard due to improper handling Equipments and machines.	Ensure that the m/c machine are properly carried.
5	Start the Programming work grinding/drilling if required	Trained and experined persons from contractors	As per attached hazards categories	Ensure that all work must be done by train person. Hand Gloves, safety goggles, must be required.
6	Removal of scraped material after work completion.	Contract Employees	Waste Cables	safety shoes, cotton hand gloves
7	Closing of Permit	Permit Executor and contractor	Violation of Permit	The permit should be handed over after getting it signed from Executor.

E

Special Instructions/Note:

- 1 Get the permit to work along with height work permit from authorized person
- 2 Follow all the work instruction's strictly as per work permit
- 3 The switch board used must have ELCB
- 4 No cable Joints in portable electric equipment is acceptable.
- 5 Close Supervision while performing the work.



(DIRECTOR)
YOGESH SOMGIR