

Date 24.7.2024

Safe Work Procedures

PGSTPL Follow the safe work procedures is highly dependent on the availability and accuracy of the input data, When provided with complete Input data, a higher confidence on the validity and robustness of the results are obtained. The example of data collection will be specific to operations, building design, personnel / population occupancy levels.

Sr. No.	Activity	Hazard	Available control Measure
1	Welding	Electric Shock	Earthing to machine, Leather hand gloves and safety shoes.
		Eye irritation	Gelding shield and goggles
2	Hand grinder	Cutting & grinding dust	Eye goggles
		Electric Shock	Leather hand gloves and safety shoes.
3	Drill M/C	Electric Shock	Earthing to machine, Leather hand gloves and safety shoes.
		Vibration	Anti vibration handle.
4	Plasma Cutting	Electric Shock	Earthing to machine, Leather hand gloves and safety shoes.
		Eye irritation	Gelding shield and goggles
5	Material loading/unloading	slippage	Proper cotton strong belt.



For PGS Technologies Pvt. Ltd.