



	ONTRACTOR : CERULEAN ENVIRO TECH PVT. LTD.				
.NO.	Task	Hazardous and Risk	Control Measures	Remarks	
	ion and Planing:				
1	Access to Work Area	14) Clim Trip and fall bazard	1) Walkaway must be cleared of materials		
			2)Good housekeeping to be maintained continuosly		
		2) Injury due to Falling objects	1) Worker must be saftey inducted		
			2) Tool box talk must be conducted prior to start of work		
			3)Workers must be instructed to respect baricade		
		3) Stuck by moment of vehicle	1) Follow Traffic Management at site		
	Loading & Unloading of material and Equipment at site	3) Stuck by moment or vernors	1)Use PPE's like saftey shoes, Helmet & Hand Glows		
2		1)Pinch Point, Cuts,Abrasion	2)Ensure that the material is kept on Wooden Donage		
			3) Deploy Sufficient manpower and continious supervision		
		a)S. in Country	1) Use manual material handling technique		
		2)Strain, Sprain	2) Activity should be carried out under supervision		
		3)Injury due to fall of material on foot	1)Use PPE's like saftey shoes, Helmet & Hand Glows		
			2) Deploy Sufficient manpower and continious supervision		
		4) Injury to other personal while	1)Area to be barricated		
		unloading long project	2)Activity should be carried out under supervision		
			1) Driver should not leave the vehicle		
		5) Accidently movement or start of vehicale	2)Handbreak must be applied when vehicle is parked		
			3)Wheel stopper must be used		
			4)Area to be barricated		
			1)All power tools,hand tools must be inspected & tested		
	Installation power dist board	1) Injury to damaned power tools and slipping of hand tools	before start to work		
			2)Only trained operator to operate the power tools		
3			3) Right tools for the right job		
,			1)No cable joints to be allowed		
		2) Shock	2)All the connection to be through industriel pin tops		
			3)Ensure proper earthing		
4	Panel Shutdown	1) Shock	1) Ensure the supply is properly cut off		
			2)Apply lock out & tag out system		
			3)Deploy 1 person from continous sepervsion		
			4)Wear shockproof handgloves		
		2) Hand injury due to defective hand too	1) Use Right tools for the right job		
			(2) Use appropriate PPE's		
5	Clean up wortk area and dispose of all subrish in bins	1)Environmental Impact	1)Ensure all material off-cuts and rubbish is removed as		
			the are generated and disposed off in appropriete		
			recepacles 2) Ensure all material / tools and quipment are removed		
		· ·	LA Ensure all material / tools and dulpment are removed.		

The above SWMS is a standrad documenta. However any other site specific risks over and above listed in this document should be evaluted and addresed before commencement of the work

The team member involved in the aforesaid tasks should be briefed or the SWMS before commencing work.

Team members should ensure that work is immediatly stopped. If the SWM is not being followed

Registered office: "Payas", 25 Madhavbaug Society, Shivtirthanagar, Paud Road, Pune 411038

http://www.cerulean-envirotech.com

+91 8956324914

