


## **SOP (Standard Operating Procedure)**

- **While working in Company, before work can commence, properly complete all work permits, safety induction meetings, etc.**
- **Our motive of company for safety is use three (Safety Shoes, Safety Helmet and Mask and carry three (Hand gloves, Safety Goggles and Ear Plugs.)**
- **Equipment inspections will be completed by qualified personnel.**
- **While working on height, insure life line or arrange life line to tie double harness safety belt.**
- **Establish the scope of work, and ensure everyone knows their specific job duty.**
- **While doing welding work the workmen should wear full welding apron.**
- **As before any work, please ensure all tools and tackles in good condition no any tear/cutting of wire of any equipment.**
- **Fallow all guidelines regarding work and company policy.**
- **Before working on site the workmen fully insured by medical insurance.**
- **Regular safety training provided to workmen.**



Authorized Signature