



S.R. ENGINEERING SOLUTIONS

Authorised Distributors of Valvoline Cummins Ltd & ALP Aeroflex Pvt Ltd.
Authorised Sale and Service Dealer of the Lucas-TVS
Deals in: Ducting & Insulation Work, SS & MS Fabrication Work and Civil Works.

Tool box safety meeting



We Take Tool Box safety meeting of all of our employees at our store per day before moving to working site. In this session our Supervisor check our tools, PPE and safety equipment's condition and availability required for work.

Checklist for Tool Box and Safety Equipment:

S.N	Tools/Safety Equipment/Activity	OK	Not OK
1	Check the condition and availability of all PPE's for every employees(e.g. helmet, shoes, gloves, glasses etc)		
2	Check the condition and availability of safety equipments like Safety Belt, Lanyard etc for height work		
3	Check the condition and availability of equipments like Fire Extinguishers, Sand and water bucket, Fire blanket, Face shield, Leather Gloves etc for Hot work, Gas Cylinder Etc		
4	Check the condition of Welding Machine, Earthing, ELCB Tripping and leads etc for Hot Work.		
5	Check the insulation of Pliers, Screw Drivers/Tester etc for Carrying out Electrical Work		
6	Check the condition and availability of ladders/scaffold, Their Wheel chocking system etc before going for Height Work.		

solutions



Tool box safety meeting

We Take Tool Box safety meeting of all of our employees at our store per day before moving to working site. In this session our Supervisor check our tools, PPE and safety equipment's condition and availability required for work.

Checklist for Tool Box and Safety Equipment:

S.N.	Tools/Safety Equipment/Activity	OK	Not OK
1	Check the condition and availability of all PPE's for every employees(e.g. helmet, shoes, gloves, glasses etc)	✓	
2	Check the condition and availability of safety equipments like Safety Belt, Lanyard etc for height work	✓	
3	Check the condition and availability of equipments like Fire Extinguishers, Sand and water bucket, Fire blanket, Face shield, Leather Gloves etc for Hot work, Gas Cylinder Etc	✓	
4	Check the condition of Welding Machine, Earthing, ELCB Tripping and leads etc for Hot Work.	✓	
5	Check the insulation of Pliers, Screw Drivers/Tester etc for Carrying out Electrical Work	✓	
6	Check the condition and availability of ladders/scaffold, Their Wheel chocking system etc before going for Height Work.	✓	