



Govt. Licensed Electrical contractor

RS ENGINEERING SERVICES

9-B, Ramanand colony, Jalna Road, Opp. Doodh Dairy, Kranti Chowk, Aurangabad - 431 001. E-mail :123rsengineeringservices@gmail.com
Branch Office : Shop No. 1065, K-232/33, Muley I - Square , MIDC, Waluj, Aurangabad - 431 136.

• Cell : 9371054171. • MC No. : 17634 MS No. : 33852 • GST No. : 27AVBPS9251K1Z1 • PAN No. : AVBPS-9251K

TO,
ENDURANCE TECHNOLOGIES LTD,
K-226/2 ,MIDC WALUJ,
AURANGABAD.

Date & 20/01/2023

SUB -: DECLARATION OF SAFE WORK PROCEDURE

FOLLOWING POINT WILL BE CONSIDERED WHILE DOING ELECTRICAL WORK :

- 1) SWITCH OFF THE LINE BEFORE STARTING WORK.REMOVE THE FUSES.OPEN THE DOOR OF COMPARTMENT.PUT A NOTICE BOARD ON THE COMPARTMENT FOR LOCKOUT/TAGOUT CONTROL HAZARDOUS ENERGY & PROTECT WORKERS FROM HARM.
- 2) CHECK WHETHER SUPPLY IS OFF.
- 3) WHILE DOING WELDING WORK ,PLEASE CHECK NO ONE IS THERE IN THE CONNECTED AREA.PLEASE KEEP A BUCKET FULL OF WATER & FIRE EXTINGUISHER NEARBY.PLEASE USE WELDING GOGGLE.MARK THE AREA WHERE WELDING MAY AFFECT.
- 4) WHILE WORKING AT HEIGHT,USE FULL HARNESS SAFETY BELT.IF THERE IS NOT ANYTHING TO HANG THE SAFETY BELT,WE HAVE TO FIRSTLY INSTALL A LIFE ROPE & THAN AFTER HANG THE SAFETY BELT HOOK.
- 5) ALWAYS USE ALL SAFETY EQUIPMENTS SUCH AS SAFETY SHOES,HELMETS,BELTS,ETC.
- 6) SUPERVISOR/PLANT ENGINEER SHOULD BE PRESENT AT THE SITE WHILE WORKING.
- 7) ALWAYS WORK WITH CALM & QUITE MIND.
- 8) DO NOT PUT PRESSURE FOR FAST WORK.

For R.S. Engineering Services


Proprietor