

SR NO	CHECK LIST OF DRILING MACHINE	
1	Machine is physically sound and in working condition	OK
2	All power cable are free from damage.	OK
3	Flexible cable are provided to avoid prevent cable damage.	OK
4	Dead man switch is damage free and in working condition.	OK
5	Availability of handle for better grip and control.	OK
SR NO	CHECK LIST OF MULTIMETER	
1	The multimeter's impressive versatility is owed to its ability to test for the three basic units of electricity	OK
2	Voltage: Multimeters can test two forms of voltage: alternate current (AC) and direct current (DC).	OK
3	Resistance: Resistance is the opposition to the flow of current through a circuit, and is measured in Ohms.	OK
4	Current: Generally speaking, current is the amount of electricity flowing through the circuit, and is measured in amps.	OK
SR NO	CHECK LIST OF SCREWDRIVER	
1	Always match the screwdriver to the screw head, both in terms of size and type.	OK
2	Choose contoured handles that fit the shank tightly, with a flange to keep the hand from slipping off the tool.	OK
3	Use a slot screwdriver with a blade tip width that is the same as the width of slotted screw head.	OK
4	Use a vise or clamp to hold the stock if the piece is small or moves easily.	OK
5	Wear safety glasses or a face shield (with safety glasses or goggles) that is appropriate for the hazards of the work you are doing.	OK

RISHABH 410

MULTIMETER



REL AUTO MAN Hz % HOLD

OFF Ω \rightarrow \leftarrow

V~ V= °C mA= A=

A~ mA~ V~

CE Hz/%

\perp V Hz \rightarrow \leftarrow mA A

1000V 400mA 10A

1000V CAT III











STANLEY

500W/600
220-240V
5.4A/10A
1.2m

Made in PRC

0 28 57 2



Stanley Europe - 31200 Mellebeke Belgium

21

