

# ACTION EVIDENCIES---Occurrence

---

BEFORE



Insert clamping nut head got damaged hence unable to do the proper tightening where earlier replacement Frequency was 5000 Nos./Nut

AFTER



Nut changed frequency reduced by 20 % From 5000 Nos./nut to 4000 Nos./Nut