


Corrective Action: Occurrence - Pad Separation Concern 520BS01006 Frt LH Pad

| TYPE | Identified Root Cause | Corrective Action | Resp | Target Date | Status |
|------------|---|---|------|-------------|-----------|
| Occurrence | Due to presence of relief in bottom side of single chamber baking oven , Fallen parts might have lodged in the corner of oven and missed during collection using magnetic trolley | Relief in all single chamber ovens will be covered with mesh in order to prevent part entry into the corner of the oven | PED | 20-10-2024 | Completed |

Before



After



Mesh provided in bottom side of oven to prevent part entry into the corner of the oven

Corrective Action: Occurrence - Pad Separation Concern 520BS01006 Frt LH Pad

| TYPE | Identified Root Cause | Corrective Action | Resp | Target Date | Status |
|------------|---|---|------|-------------|-----------|
| Occurrence | Due to lack of awareness on over baking fallen part mixed up with regular batch | 1) Awareness provided to baking operators on fallen part collection and handling 2) Fallen part verification will be done by quality team on daily basis | QAD | 03-10-2024 | Completed |

Fallen Part Handling Awareness Provided to Baking Operators

