

Customer Complaint :-Incomplete Head Forming

After



Die locking bolt replaced with new one and tighten.