Customer Complaint :-Incomplete Head Forming

Before



Die locking bolt observed loose in forging 2nd stage