





QUALITY ALERT


Customer	Customer Complaint No	Complaint Type	Date of Complaint
Singla Forging/ETL	~	Fitment	
Customer Location	Part Name	Qty Reported	03-05-2022
PANTNAGR	Socket Head Bolt	1	
Complaint Reported By	Complaint Received By	Customer Part Number	
Mr.Rahul/Anuj Kumar	Mr. Nishant	F2LY00312B	


Complaint Description :

Uneven face/cut marks of Copper Washer resting area in Socket Head Bolt

NOT OK PHOTO	OK PHOTO
	

ICA : 100% material lying at customer end and in-house to be segregated.

Prepared By :	Approved By:	 ICA Identification Mark
Amit Kumar	Nishant Jangra	

Distribution List			
WORK STATION <input checked="" type="checkbox"/>	HOD MATL <input type="checkbox"/>		Identification Mark not Feasible Before Plating due to Black & Oiled Surface
HOD Prod <input type="checkbox"/>	HOD PROCESS <input type="checkbox"/>		
HOD QA <input type="checkbox"/>	PLANT HEAD <input type="checkbox"/>		