

Before

OPL not present in final instection for burr fold in part hole