



AURANGABAD PRESSINGS

CORRECTIVE ACTION PLAN IN 6 W - 2H FORMAT

Month :- Jun 2023

CUSTOMER :- ENDURANCE TECH. LTD. PANTNAGER

Legends : **What** - Defect Phenomenon **Why** - Cause Side-Indicate Root cause. **Who** - Responsible Person

Which - Shop / Cell / M/c / Stage **Where** - Process / Operation stage **How Much** - Defective Qty. **When** - Target date for action completion.

ITEM CODE :- B2SG00426 O

ITEM NAME :- CBS LINK C101

Sr.	What	Which	Where	Why	How Much		Inspection Side			Sustenance		
					Actual	Target	CAUSE SIDE		Before		After	Status
							BEFORE	AFTER				
1	Plating miss OR White patches on surface.	CBS LINK C101	Plating shop	Plating miss OR White patches on surface. Why:-1- Passivation not Adiquated. Why:- 2- Component Engaging in each other . Why:-3- Large qty.of lot during passivation process.	647	0	Large qty.of lot during passivation process.	Reduce passvation lot quantity during passivation process not Engaging each other.	Before no inspection for plating .	1) 100% inspection before dispatch for plating issue. 2) Training given to inspector.	Implement ed

Prepared By :

Approved By: