



Non conformity details:

Bracket ABS MTG Not Rest on ABS Modulator.



Root Cause of Non Conformity:

Bracket ABS MTG Flattness Not OK

Corrective Action:



New Flattning Tool for Bracket ABS MTG implemented.

Responsibility	Target