

AURANGABAD PRESSINGS

Corrective / Preventive Action

Doc. No. :F/18
Rev. No. : 00
Date :05.01.2011

Couustomer Name: Endurance Technology Ltd., K226/2


Date : 20.10.2023

Part Name: Bracket ABS MTG


Part No: B2SU01102 O

Non conformity details:

Bracket ABS MTG Not Rest on ABS Modulator.



Before



After

Root Cause of Non Conformity:

Bracket ABS MTG Flattness Not OK

Corrective Action:



New Flattning Tool for Bracket ABS MTG implemented.

Responsibility

Target

Preventive Action:

- 1) Flattning operation added for Bracket ABS MTG.
- 2) Operation Sequence To Be changed from next lot.

Responsibility

Target

P.D.Kulkarni

20.10.2023

| Before | |
|--------|-------------|
| | Blanking |
| | Piercing |
| | ETL Logo |
| | 1st Forming |
| | 2nd Forming |

| After | |
|-------|-------------|
| | Blanking |
| | Piercing |
| | 1st Forming |
| | ETL Logo |
| | 2nd Forming |

Revision of System document if any:-

Implementation verified by:-

Effectiveness verified by:-

After three months:-

Verified By

HOD. QA