BEFORE	AFTER
tatus: Marking not done to detect inspection at varehouse	Status: 100% marking started after inspection for flatness & broken at warehouse