## **Before & After**

**Component** :- Fork Bolt

**Stage** : **Final inspection** 

**Date of Implementation:** 22.01.2024

## **BEFORE**



## **AFTER**



coolant direction is wrong..

Correct the coolant direction & coolant is on tap. Hence burr easily remove from tapping.