

Format Number : SQA /053

Revision Number : 00



Revision Date : 01.02.2022

ANANT ENTERPRISES


QUALITY ALERT

QA NO :- 4

Customer	Customer Complaint No	Complaint Type	Date of Complaint
ETPL		Fitment	
Customer Location	Part Name	Qty Reported	16-03-2024
NURSAPURA	KONA OUTER TUBE RH/LH	7 nos	
Complaint Reported By	Customer Part Number		Defective Part Batch Code
ETPL	F2BF367070 / F2BF368070		
Complaint Received By			
Anant Ent.			

NOT OK PHOTO	OK PHOTO
Actual: M6X1-6H thread missing in part.	Specification: M6X1-6H thread in part
	

CONTAINMENT DOT IDENTIFICATION MARK ON M6 FACE.
100 % Visual verification of M6 thread.

Prepared By :	Approved By:	 <p style="margin-top: 10px;">ICA Identification Mark</p>
BHAGYESH K	Mallappa Belavi	

Distribution List				Photo after dot mark	
WORK STATION	<input checked="" type="checkbox"/>	HOD MATL	<input type="checkbox"/>		
CC	<input type="checkbox"/>	HOD PROCESS	<input type="checkbox"/>		
HOD Prod	<input type="checkbox"/>	HOD AE	<input type="checkbox"/>		
HOD QA	<input type="checkbox"/>	PLANT HEAD	<input type="checkbox"/>		
				ICA details e.g.:	

Note : - This document needs to be filled, controlled & monitored by Quality Engineer.
 - This document can be removed after one month of inclusion of Firewall at concerned workstation