## **ACTION EVIDENCIES --- Detection**

**BEFORE** 

**AFTER** 





PPG observed in Wearout Condition

New Carbide PPG Procurement Done