


## Countermeasure



**Machining oil layer was found to be present in some thread area.**



**Hot water cleaning started at 40~50° degree temperature for avoid oil content from part**