

Operator having inadequate knowledge of Oiling Work instruction to Detect Mixup
issue at Process