1- Clutch Plate cleaning have not started after grinding process.

2- 100% Inspection not done after cleaning process…