




METHOD STATEMENT

1. Ensure that the correct equipment for each job.
2. All tools and machinery properly guarded.
3. Ensure operators are trained to use the tools, equipment and machinery safely.
4. Provision to be made to safely store or dispose of waste / off-cuts.
5. Ensure enough work space around machinery.
6. Ensure all tools, equipment and machinery is regularly maintained.
7. Ensure there is a process to ensure that tools and machinery are switched off before maintenance and cleaning is carried out and cannot be inadvertently started by other workers during maintenance and cleaning.
8. Unsafe or faulty tools, equipment or machinery should be tagged out, removed from use until they are repaired or replaced.
9. Machine repairs to be always carried out by authorised and competent persons only.
10. Ensure health and safety risks are considered before modification or alteration of any tools, equipment or machinery.
11. Ensure appropriate fall prevention methods been implemented for all tasks that are undertaken for work at height. (e.g. guardrails, scaffolds, harness systems)
12. Ensure to conduct pre-operational checks.
13. Ensure Safe work procedures are in place.
14. Ensure appropriate PPE is provided and used wherever applicable.
15. Ensure Outlets, plugs, sockets, leads and power points are in good condition.
16. Ensure Power circuits are protected with appropriately rated fuses or circuit breakers.



VacSeal

Vacuum Impregnation Services




+91 7722060077 / 88

info@vacseal.co

www.vacseal.co



17. Electrical equipment is never used in 'wet' areas.
18. LockOut Tag Out system to be used for the machine maintenance.
19. Welding equipment if used then it should be used according to the manufacturer's recommendations.
20. Non-flammable welding screens/partitions are used.
21. Signs warn that welding is taking place, and entry to the work area is restricted and ensure there is adequate ventilation.
22. Fire Extinguishers are kept ready on the work site in case of fire hazard.
23. Ensure all safety and work permits are issued by the concerned authorities on the work site.



SEALING BEYOND BOUNDARIES

Vacuum Impregnations (India) PVT LTD

J-249 & 250 MIDC Industrial Estate, Bhosari, Pune – 411026, Maharashtra

CIN NO U29299PN1897PTC105817



Proudly Indian