C Engineers	PRAGYA ELECTRICALS		
 Licenced 'A' Class Electrical Contractor Consultant GST No. : 27ACEM3656Q1ZY Panel Manufacturer Supplier (All Electrical Items) 			
		Industrial Erection & Maintenance (H.T.& L.T.)	

43

Date :

Method Statement

Ref.:

The functions & responsibilities of this committee are to:

- 1. Prior to the work, wear safety shoes, goggles & gloves. It is also advice to place a fire extinguisher near the site during brazing.
- 2. Prepare all tools & equipment to be used in replacing the refrigerant compressor like gas cylinder, gauge manifold, brazing set, brazing rod, flaring tool, spanner, wrench, screw driver, etc.
- 3. Remove the refrigerant from the system.
- 4. Use Loto For Tagout/Tagin before starting the work.
- 5. Check out whether power is off or not before touching the equipment.
- 6. Dismantle the equipment from the panel & then start the maintenance work.
- 7. After completing the work check the equipment that all parts will be connected properly.
- 8. If everything is ok then start the power & check the supply.



St Mansing Fa.