

46 7  
**FOR THOSE WHO WANT THE BEST**

- Engineers
  - Licenced 'A' Class Electrical Contractor
  - Consultant
  - Panel Manufacturer
  - Supplier (All Electrical Items)
  - Industrial Erection & Maintenance (H.T.& L.T.)
- GST No. : 27ACEM3656Q1ZY

**PRAGYA  
ELECTRICALS**

Off. : Rashmi Vihar, Near Panchavati Hotel, Padampura, Aurangabad - 431 005.  
Mob. : 9371777808 / 9326049395 / 9325235999 E-mail : electricalspragya@yahoo.com / electricalspragya@gmail.com


Ref. :

**Safe Work Procedure**

Date :

Following points will be considered while doing electrical work:

1. Switch off the line before starting work. Remove the fuses. Open the door of compartment. Put a notice board on the compartment or a LOTO on the compartment for lockout/tagout control hazardous energy & protect workers from harm.
2. Check whether supply is Off.
3. While doing welding work, please check no one is there in the connected area. Please keep a bucket full of water & fire extinguisher nearby. Please use welding goggle. Mark the area where welding may affect.
4. While working at height, use full harness safety belt. If there is not anything to hang the safety belt, we have to firstly install a life rope & than after hang the safety belt hook.
5. Always use all safety equipments such as safety shoes, helmets, belts, etc.
6. Supervisor/Plant Engineer should be present at the site while working.
7. Always work with calm & quite mind.
8. Do not put pressure for fast work.



*S. M. Kausik*