

**HIRA BEFORE COMMUNICATION AND CONTROL**

Followings are the details which we have discussed and guided to our employees before starting the actual work.

| SR NO. | JOB STEP   | HAZARD RISK                  | HAZARD CONTROL  |
|--------|--|------------------------------|---|
| 1.     | Structure and Module mounting work on the roof top | Fall down from height        | Use safety belt ,safety helmet ,safety shoes and lifeline       |
| 2.     | Material shifting by crane                         | Fall down object from height | Keep safe distance from the object ,use helmet and safety shoes |
| 3.     | DC and AC side wiring work                         | Chances of Electrical Shock  | Wear Electrical hand gloves                                     |
| 4.     | Cable tray cutting work                            | Chances of injury            | Wear glasses, hand gloves and apron                             |

**FOR**



**OSCILLATION ENERGY LLP**

Oscillation Energy LLP  
Plot No 52, Gut No 96,  
Anjali Tower, Naik Nagar,  
Aurangabad- 431005  
Email ID: [oscillationenergy@gmail.com](mailto:oscillationenergy@gmail.com)

GSTN : 27AAGFO0348B1ZN  
Bank A/C No: 493801010036721  
IFSC : UBIN0549380  
Cell No : 8329840186/ 7020953245