WORK PROCEUDER

- 1. TAKEN PERMIT BY AUTHROIZED PERSON
- 2. TAKEN TOOL BOX TALK
- 3. SURFACE PREPRATION
- 4. ACP CLADDING
- 5. STRUCTURAL GLAZING
- 6. ALUMINIUM MESH
- 7. CLEAN THE WORKING AREA /PLACE.

For Alu Mine Fabricators India Pvt. Ltd.



Authorized Signatory