

M/S SHRIPAD ELECTRIC WORKS

DRILL MACHINE ACTIVITY METHOD STATEMENT

SR.NO.	DESCRIPTION
1	ENSURE CABLE CONDITION .
2	CHECK SEFTY COVER OF MACHINE
3	ENSURE AVAILABILITY OF PIN TOP.
4	CHECK FIRE EXTINGUISHER AVAILABILITY.
5	ENSURE HELPER AVAILABILITY.

PREPARED BY



APPROVED BY



M/S SHRIPAD ELECTRIC WORKS

WELDING MACHINE ACTIVITY METHOD STATEMENT

SR.NO.	DESCRIPTION
1	CHECK WELDING HOLDER CONDITION.
2	CHECK EARTHING CLAMP CONDITION.
3	CHECK WELDING CABLE CONDITION.
4	CHECK EARTHING CABLE CONDITION.
5	ENSURE AVAILABILITY OF PIN TOP.
6	CHECK LUG CONNECTION / THREAD CONNECTION.
7	CHECK PHYSICAL CONDITION OF MACHINE BEFORE OPERATION.
8	CHECK FIRE EXTINGUISHER AVAILABILITY.
9	CHECK WATER BUCKET AVAILABILITY.
10	CHECK HOUSE KEEPING CONDITION OF WORKING AREA.
11	ENSURE HELPER AVAILABILITY.



M/S SHRIPAD ELECTRIC WORKS

GRANDER MACHINE ACTIVITY METHOD STATEMENT

SR.NO.	DESCRIPTION
1	ENSURE CABLE CONDITION .
2	CHECK SEFTY COVER OF MACHINE
3	ENSURE AVAILABILITY OF PIN TOP.
4	CHECK FIRE EXTINGUISHER AVAILABILITY.
5	ENSURE HELPER AVAILABILITY.

PREPARED BY

