



Amar Engineers

CHECK LIST FOR COMMON TOOLS / METERS

Sr No	Tools	Physical condition (Damage / Bend)	Condition of insulation	Condition of Cutting edge	Condition of Tightening edge	Battery status	Testing	Condition of testing wires
1.	Plier	A	A	A	NA	NA	NA	NA
2.	Screw driver	A	A	NA	A	NA	NA	NA
3.	Tester	A	A	NA	A	NA	NA	NA
4.	Screw spanner	A	NA	NA	A	NA	NA	NA
5.	Fix spanner set	A	NA	NA	A	NA	NA	NA
6.	Ring spanner set	A	NA	NA	A	NA	NA	NA
7.	Megger	A	NA	NA	NA	A	A	A
8.	Multi meter	A	NA	NA	NA	A	A	A
9.	Clamp meter	A	NA	NA	NA	A	A	A

A = APPLICABLE

NA = NOT APPLICABLE