



OM SAI ENTERPRISES

STRUCTURE, PIPELINE, FABRICATION & ERECTION

RH-107/4, Sainagar, Bajaj Nagar, MIDC Waluj, Aurangabad-431136.
Mob. 8446420842, 7276761520

Ref.

Date : 16 / 01 / 2023

TO,
ENDURANCE TECHNOLOGIES LTD,
K-226/2, MIDC WALUJ,
AURANGABAD.

SUB -: Safe work procedure

FOLLOWING POINT WILL BE CONSIDERED WHILE DOING FABRICATION WORK :

- 1) SWITCH OFF THE LINE BEFORE STARTING WORK.REMOVE THE FUSES.OPEN THE DOOR OF COMPARTMENT.PUT A NOTICE BOARD ON THE COMPARTMENT FOR LOCKOUT/TAGOUT CONTROL HAZARDOUS ENERGY & PROTECT WORKERS FROM HARM.
- 2) CHECK WHETHER SUPPLY IS OFF.
- 3) WHILE DOING WELDING WORK ,PLEASE CHECK NO ONE IS THERE IN THE CONNECTED AREA.PLEASE KEEP A BUCKET FULL OF WATER & FIRE EXTINGUISHER NEARBY.PLEASE USE WELDING GOGGLE.MARK THE AREA WHERE WELDING MAY AFFECT.
- 4) WHILE WORKING AT HEIGHT,USE FULL HARNESS SAFETY BELT.IF THERE IS NOT ANYTHING TO HANG THE SAFETY BELT,WE HAVE TO FIRSTLY INSTALL A LIFE ROPE & THAN AFTER HANG THE SAFETY BELT HOOK.
- 5) ALWAYS USE ALL SAFETY EQUIPMENTS SUCH AS SAFETY SHOES,HELMETS,BELTS,ETC.
- 6) SUPERVISOR/PLANT ENGINEER SHOULD BE PRESENT AT THE SITE WHILE WORKING.
- 7) ALWAYS WORK WITH CALM & QUITE MIND.
- 8) DO NOT PUT PRESSURE FOR FAST WORK.

