



SMASH ELECTRICALS

- + All type H.T./ L.T. Electrification
 - + All Type A.C. / D.C. Motor Rewinding
 - + All type Fabrication
 - + All type M/c. Pannel Makers (M.C.C., P.C.C.)
 - + Refirigation (m/c. A/c.)
 - + Qualified Electrical Supply on Contract Basis
 - + All Types Contol Pannel .
- GSTIN : 27AHQPR6358F1ZP**

Plot No. C - 113, Near Dhanvantari Hospital More Chowk, MIDC Waluj, Aurangabad - 431 136.
☎: 0240 2556216 Mobile : 9325147813, 9325147814, 9325147811, 9823189605. email smashgroup3@yahoo.in

To.

Kind Attan.:

Safe Work Procedure

Subject:

Following points will be considered while doing electrical work:

1. Switch off the line before starting work. Remove the fuses. Open the door of compartment. Put a notice board on the compartment or a LOTO on the compartment for lockout/tagout control hazardous energy & protect workers from harm.
2. Check whether supply is Off or Not.
3. While doing welding work, please check no one is there in the connected area. Please keep a bucket full of water & fire extinguisher nearby. Please use welding goggle. Mark the area where welding may affect.
4. While working at height, use full harness safety belt. If there is not anything to hang the safety belt, we have to firstly install a life rope & than after hang the safety belt hook.
5. Always use all safety equipment's such as safety shoes, helmets, belts, etc.
6. Supervisor/Plant Engineer should be present at the site while working.
7. Always work with calm & quite mind.
8. Do not put pressure for fast work.
9. After completing the work, check properly that there in not any harmful damages of any equipment or any other substance, no injury to any person, not any electrical short circuit, etc.



◆ 24 Hours Safe & Quick Work Service ◆