



Company Logo		HAZARD IDENTIFICATION & RISK ASSESMENT			Company Name & Address
Team Members - Mr Amit Aradhya, Mrs Sheetal Aradhya, Mr. Pinjarikar					
S. No.	Activity/Job Steps	Hazard Identification	Risk Trigger/ Effects	Mitigation Measure/Preventive Action	Monitoring by (Department responsible)
1	Shot Blasting Machine Erection By Crane	1. Fitness of Crane.	1. May result in accident due to unfit condition of crane.	Vehicle in OK Condition	M/s. Precicut Engg.
		2. Unauthorized Driver.	2. Legal issue if any accident takes place.	Driving Licences	M/s. Precicut Engg.
		3. Unskilled Manpower.	3. Due to lack of knowledge chances of accident.	Skilled operator	M/s. Precicut Engg.
2	Assembly of Machine	Falling from height	Physical Injury	1) Safety belts 2) Safety Helmet 3) Stack Holder	M/s. Precicut Engg.
3	Electrical Work	Electrical Hazard	Electrical Shock	1) Licences operator 2) Safety Shoes 3) Rubber hand gloves	M/s. Precicut Engg.
4	Welding Work	Hot Work Hazard	Burn injury	1) Skilled operator 2) Safety Shoes 3) Hand gloves 4) Apron 5) Face Shield	M/s. Precicut Engg.

For Precicut Engineers

*Mrs Aradhya*  
Proprietor

APPROVED BY (Proprietor-Name & Sign.)

*Mrs Sheeta Sharad Aradhya*

PREPARED BY (Engineer/Supervisor)