

ENDURANCE TECHNOLOGIES LIMITED METHOD STATEMENT FOR PARTITION FABRICATION

i	OB SAFETY A	NALYSIS: - I	PARTITION FABRICATION FOR	ACCOUNTS DEPARTMENT

VENDOR NAME: REA THERMAL PVT LTD

Date: 17.01.2023

Golden Safety Rules: Use of Work permit, Minimum PPEs - safety helmet, refective vest, safety shoes, No Supervison no work, only train and medically fit persons to deploy for work, area barricatio, house keeping at work location, all lifting tools and Tackles shall be certified by third party and defect free.

SR.	ACTIVITY	LOCATION	SUB-ACTIVITY	HAZARÐ	RISK	Control measure	RESPONSIBILIT
1			REMOVAL OF EXISTING CARTOONS AND PACKAGING MATERIAL FROM THE MAZNINE FLOOR	Slippage, Body part damage, pinch point, work in pit, Trip & fall	Body part Injury	Use of Proper Tools & tackles during work, Use of Safety PPE's, Proper access & egress ladder, barricode the area & pit, Closing all the Hyd connection ports (Sealing), Confined Space	
2			SQUARE MESH	Accident during Maintenance,fire,energy, sharp edges, electricity, Pinch point	FIRE, Shock, Body part Injury	Keep fire extuingwisher near the welding area, use properly when required Switch Off Main electrical Power Supply of Machine & provision of Use of Safety PPE's, Safety helmet, shoes, handgloves, welding apron, etc,	Site Supervisor - REA THERMAL
3	PARTITION AS PER PLANT LAYOUT -ON	arrangement ON HYDRA or manual lifting	Slippage, body part cut / damage, pinch point, Sharp Edge, lack of ventilation	Body part Injury	Use of Proper Tools & tackles during work, Use of Safety PPE's, Testing of Wire ropes & Hotst / Crane/ manual lifting, Scaling of hyd hoses & connector, Confined space	Site Supervisor - REA THERMAL	
4	ACCOUNTS DEPARTMENT	MAZNINE FLOOR ABOVE STORES	Fixing PP shets above partition area	Slippage, body part cut / damage, Sharp Edge, Pinch point, lack of ventilation	Body part Injury	Use of Proper Tools & tackles, Use of Safety PPE's, Confined Space, Testing of wire ropes & hoist / Crane, web bcd for wooden blocks	Site Supervisor - REA THERMAL
10		-	Painting to fabricated area	Slippage, body part cut / damage, Sharp Edge, pinch point	Body part Injury	Use of Proper Tools & tackles during work, Use of Safety PPE's, confined Space	Site Supervisor - REA THERMAL
			Top side area cleaning, welding of structure M.S. channel, PIPES etc cleaning	Slippage, body part cut / damage, Sharp Edge, pinch point, Eye injury due to		Use of Proper Tools & tackles during work, Use of Safety PPE's, confined Space, proper welding screen, apron, welding gloves, shoe cover, safety shoes.	Site Supervisor - REA THERMAL
11			Removing the LOTO. Switch ON Power Supply & Trial of Machine	Accident during Maintenance, energy, Fire, electricity	Shock, Body part Injury	Use of all Electrical Safety PPE's, Use of Safety Shoes, Handgloves, Measuring Instrument like Multimeter,	ETPL Suprvisor & Site Supervisor - REA THE

Prepared	By:
----------	-----

Name:

Review By:

Name:

Approved By:

Name:

Signature:

Signature:

Signature:

REA Thermal Fet. Ltd

Directo



ENDURANCE TECHNOLOGIES LIMITED

		K226/2 DISC BRAKE UNIT -Waluj MIDC				
Date	T	17.01.2023				
Contractor		REA THERMAL PVT LTD				
Work location	MAZNINE FLOOR ABOVE STORES BSR AREA					
Scope:	METHOD STATEMENT FOR PARTITION FABRICATION FOR ACCOUNTS DEPARTMENT					
Sr no	ITEM OF WORK					
A	ACTIVITY	METHOD STATEMENT FOR PARTITION FABRICATION FOR ACCOUNTS DEPARTMENT				
В	PPE REQUIRED	Hand gloves, Dust Mask, Safety Shoes, Helmet, welding screen, Safety goggles, ear plug, safety harness, WELDING SCREEN- HELMET, WELDING GLOVES, APRON ETC				
С	WORK SCHEDULE	4-5 DAYS				
D	ACTIVITY DESCRIPTION	fabrication of partition offline outside of store area. fitting ofLifting the fabricated partition and fitting with suitable partition at selected area. fitting of door for partition. fitting of PP sheets if required at fabricated parition				
		Isolation of work place free of cartons , pp sheets and papers Etc.				
		lifting and shifting of fabricated partition by Forklift or manually to dedicated location for cleaning &				
		replacement of dooricated partition, fabretc fitting.				
····-		Identification, marking, and re assly as per sequence.				
		Assly as per sequence again with farana / Over head Crane/hoist.				
E	PLANT & MACHINERY	Farana / Overhead Crane , forklift, Hand pallet Truck/ manual lifting arrangment, grinder, welding machine, lifting tools and tackles,				
6	TRADEMAN-	fitter , welder and trained REA THERMAL TEAM MEMBERS				
7	HEALTH & SAFETY	Use of PPE safety helmet,cotton Hand gloves, baricading to area, use of safety goggle, Medical Check up for all employees by MBBS doctor for fit to work at height / Confined Space, Insurance certificate,EHS Induction, PTW, Supervision, House keeping, isolation, lockout tagout of all agenies & try out.fail portion measure.				
8	WORK PERMIT	Required				
	Prepared by					
	Clients Authorized Signatery- Name and Signature					
	Audit Agency/ PMC Name and signature					

REA Thermodell