



HAZARD IDENTIFICATION & RISK ASSESMENT


Team Members - Mr Amit Aradhya, Mrs Sheetal Aradhya, Mr. Pinjarikar

S. No.	Activity/Job Steps	Hazard Identification	Risk Trigger/ Effects	Mitigation Measure/Preventive Action	Monitoring by (Department responsible)
1	Shot Blasting Machine Erection By Crane	1. Fitness of Crane.	1. May result in accident due to unfit condition of crane.	Vehicle in OK Condition	M/s. Precicut Engg.
		2. Unauthorized Driver.	2. Legal issue if any accident takes place.	Driving Licences	M/s. Precicut Engg.
		3. Unskilled Manpower.	3. Due to lack of knowledge chances of accident.	Skilled operator	M/s. Precicut Engg.
2	Assembly of Machine	Falling from height	Physical Injury	1) Safety belts 2) Safety Helmet 3) Stack Holder	M/s. Precicut Engg.
3	Electrical Work	Electrical Hazard	Electrical Shock	1) Licences operator 2) Safety Shoes 3) Rubber hand gloves	M/s. Precicut Engg.
4	Welding Work	Hot Work Hazard	Burn injury	1) Skilled operator 2) Safety Shoes 3) Hand gloves 4) Apron 5) Face Shield	M/s. Precicut Engg.



PREPARED BY (Engineer/Supervisor)

For Precicut Engineers



APPROVED BY (Proprietor-Name & Sign.)

Mrs. Sheela. Sharad.

Aradhya.