



SHUBH DEV INDUSTRIES

All Kind Of Labour Supply & Industrial Job Work

Contact.: 9766260131,9158471432 E-mail : shubhdevindustries@gmail.com

Plot No.: X - 51 MIDC Waluj Aurangabad.431136.

GSTIN : 27AXFPG6783Q1ZM

METHOD STATEMENT FOR FETTELING WORK

A

Job Description: Fettling Work- Job Work	
Area/ Location: Plant: LPDC- Fettling area	
Aux Permit Type:	NA

B

Major hazards associated with the job: 1. Electric Shock 2. Fire and Explosion 3. Slip, Trip and Fall hazard 4. Fall from height (if height work is carried out) 5. Falling Object.	6. Burn injury during Hot work 7. Eye and Cut injury During cutting work 8. Dust Fumes inhalation during drilling work.. 9. eye irritation. 10. Human Injury 11. Any Other.
---	--

What Worst can Happen?

1. Fatality or permanent disability due to Electric Shock, Amputation etc.

C

PPE's Required for Jobs: Safety Shoes, Safety glasses, Hand Gloves , Ear Plug etc.

Resources /Tools Required for the Job: Hand Tools, Chisel, and Hammer etc.

D

Activities Sequence: (What, Who & How?)

S. No	Activity	Who Will do	Risk involved	Risk Mitigation / Control Measure
1	Collect the castings after heat treatment by trolley	Operator	Sprain due to manual pushing/pulling of the trolley Falling of material at working level on the level	Safe Material handling, dedicated trolley, trained person etc.
2	Fixing the casting inside the bench vice	Operator	STF. Material Hazards, material fall down, foot Injury, Body Injury etc. Sharp edges that may	Material handling training, OJT, etc.

For SHUBH DEV INDUSTRIES

Proprietor

Page 1 of 2

