








MELTING FURNACE PPE'S REQUIREMENT		PHOTO
SR. NO.	PPE'S	
1	SAFETY SHOES	
2	HANDGLOVES	
3	FACESHIELD	
4	GOGGLES	
5	EARPLUG	
6	NOSEMASK	
7	APRON	


★ AVINASH PATANGE ★
RM-81/3
MIDC
WALUJ, AURANGABAD ★