

Sl.No	Safety Instructions
<b><u>RELATED TO PPE</u></b>	
1	Always wear Safety Shoes.
2	Avoid Metal rings/bracelets/metal watch worn during maintenance.
3	Use Insulated Tools (screw drivers / pliers/ wrench etc.,)
4	Check Instruments calibration.
5	Use Electrical safety gloves during UPS maintenance.
6	Wearing Safety goggles during UPS maintenance.
7	Service Personnel's dress is perfect and properly tucked
<b><u>RELATED TO INSTALLATION/SERVICE</u></b>	
1	Check for Insulation failure in Power/Control cables.
2	Check is there any loose connection in UPS/Battery termination.
13	Before attending fault check any Inflammable items kept inside the UPS room / Battery room.
4	Check is there any water, chemical or acid spillage near place of UPS / Battery installation.
5	Check whether direct sunlight falling over Batteries and UPS.
6	Check is there any metal items placed over or near the Battery terminals.
7	Verify is there any safety protection bypassed inside UPS.

