

Hazard Analysis Template

MMP REFRATECH						
REGD OFFICE:- B-9, SHUBHANKER,KOTHRUD,PUNE-411038						
WORK :- GAT NO. 161, CHIMBALI PHATA,CHAKAN MIDC,PUNE-410501						
PHONE:+ 91 7720090588						
WEB :- www.mmpgroup.co.in						
	PROJECT NAME:-					
	COMPANY NAME:-					
	COMPANY LOCATION :-					
	PO NUMBER:-					
	SITE ENGINEER:-					
#	Hazard Description	Risk before Mitigation Measures		Risk Elimination or Mitigation Measures	Risk After Mitigation Measures	
		Severity	Risk Hazard Index		MARGINAL	Risk Hazard Index
1	BREAKING OF WALL	MARGINAL	8	PROPER TRAINING GAVE TO THE WORKER	CRITICAL	10
2	BREAKING OF MAIN ARCH	CRITICAL	9	PROPER SUPPORT APPLIED BY METAL ROD	MARGINAL	10
3	BREAKING OF DOOR ARCH	CRITICAL	9	PROPER SUPPORT APPLIED BY METAL ROD	MARGINAL	12
4	CLEANING OF BROKEN PART	MARGINAL	13	PROPER PPE KIT GAVE TO THE LABOUR	NEGLIGIBLE	18
5						
6						
7						
8						
9			9			
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						