



# LAXMI ENTERPRISES

Plot No. W-9, MIDC, Industrial Area, Waluj, Aurangabad.  
Mob. 9545168080, E-mail : laxmigroup9@rediffmail.com



## Equipment Check list

SR NO.	NAME OF EQUIPMENT	Conditation	
		OK	NOT OK
1	Spaner Set	OK	
2	Alenky Set	OK	
3	Box Spaner Set	OK	
4	Hammer	OK	
5	Chisel	OK	
6	Plyar	OK	
7	Screw Driver	OK	
8	Hole Punch	OK	
9	Centar Punch	OK.	





# LAXMI ENTERPRISES

Plot No. W-9, MIDC, Industrial Area, Waluj, Aurangabad.  
Mob. 9545168080, E-mail : laxmigroup9@rediffmail.com



## Shot Blasting Machine Check list

SR NO	Check Point	Frequency
1	Nut Bolt Checkning For Loose & Broken	Daly
2	Checkning all gear reducer and Turbine unit	Daly
3	Shot Leval Checking	Daly
4	Checkning Rubber lining on door sealing	Weekly
5	Checkning Rubber lining In Turbine unit	Weekly
6	Conditation Of Control Case centurion plate	Weekly
7	Check Conditalon of the Shot	Weekly
8	oiling & Greasing Of Bracket & Chain	Weekly
9	Dust Collector Cleaning	Wecky
10	Replace the oil From Drive Gear Box	Weekly
11	Check the Condition of Shot Blasting Impeller Blade & Liner	Weekly

