

M/S SUNIL GANGVE

HAZARD IDENTIFICATION RISK OF ASSESMENT (HIRA)

The Following Points Should Be Followed

Sr.No	Nature of work	Hazard	Risk	Control	Residual Risk
1	While operating the machine	Bursting in the eye when air hitting the casting	High	Putting on Goggles	Low
2	Bringing The Trolley of Material To The Place of Dispatch	While Bringing The Trolley The Leg Can Be Injured And The Hand Can Also Be Injured	High	Using Safety Shoes And Hand Gloves	Low
3	Bin Washing	While Washing The Bin, Chemicals Can Get Into The Eyes And Can Injure The Hands	High	Using rubber hand gloves, wearing goggles, using gum boots	Low
4	While Transporting From The Casting Trolley	Castings May Fall On The Head	High	Using a helmet	Low
5	While Reworking	May Cause Ear Damage Hand May Be Injured	High	Using an air plug, Using hand gloves	Low

Strictly follow the rules laid down by the company

