

Shot Blasting Machine Check list

SR NO	Check Point	Frequency
1	Nut Bolt Checking For Loose & Broken	Daily
2	Checking all gear reducer and Turbine unit	Daily
3	Shot Level Checking	Daily
4	Checking Rubber lining on door sealing	Weekly
5	Checking Rubber lining In Turbine unit	Weekly
6	Condition Of Control Case centurion plate	Weekly
7	Check Condition of the Shot	Weekly
8	Oiling & Greasing Of Bracket & Chain	Weekly
9	Dust Collector Cleaning	Weekly
10	Replace the oil From Drive Gear Box	Weekly
11	Check the Condition of Shot Blasting Impeller Blade & Liner	Weekly

