



Technomat Springs Pvt.
Ltd

ONE POINT LESSON

Customer :- ETL

Problem :- Nose Burr Observed.
Spec. Burr Not Allowed
Observed:- Nose Burr Observed.
Part No. :- S2KH01402B - Rebound Spring

Date :- 25/09/2024

NOT OK



Heavy Nose Burr Observed on the spring end coil.

OK



Burr Free Ok Part.

Prepared by:- Shankar Garje

Approved By :- Anuj Shelke