



# Defect Gallery

Doc No : W03MLD970 A

Rev : 01 Date : 25-09-2024

DEPT :- Moulding / Finishing / Inspection

Customer :- M/s. Endurance Technologies Private Ltd.

PART NAME :- Bonded Bump Stop\_DIA 33 SPD P3

Part No.:- F2BW027020 & F2BW026020

Parameters		Photographs	
Visual	1 Under Cure	 NOT OK	 OK
	2 Short Fill	 NOT OK	 OK
	3 crack & Cut mark	 NOT OK	 OK
	Flash	 NOT OK	 OK
	5 Short Fill	 NOT OK	 OK
	6 Rust	 NOT OK	 OK