

QUALITY ALERT

CUSTOMER : Endurance Technology Ltd

DEFECT : Wrong bolt mixup

**BGF Part No : 8525
Customer Part No : F2LY02712B**

**Description :
M10X1.50X30_SHCS**

Complaint : Wrong bolt mixup

**Complaint No : 195/24
Date : 09.12.2024**

OK



NOT OK



Issued By (Name & Signature) : Kapil Gaikwad

Approved By (Name & Signature) : Pavan Waral