

Improvement Action:

Before

Inadequate controlling mechanism for mould delay time in moulding

After

Mould delay time controlling mechanism provided in moulding machine