
Countermeasure taken



Operation: Final inspection Target date:01.06.2022

AFTER



 After improvement plating peel off defective sample displayed at final inspection.