


□ Cause Analysis



□ Immediate Actions

Action 1 : All pipeline material has been taken for rework & all batch wise checking done on XRF thickness tester before dispatch the material , its batch wise record will be maintained .

□ Permanent Actions

Action : Plating will done on Valid parameters & its records maintained as per requirements .