

ACTION TAKEN FOR MODEL MIX UP

O.P.L (One Point Lesson)

Basic Knowledge:

Improvement Case: **✓**

Trouble Shooting Case:

OPL Theme: To avoid mix up problem in front fork spring

Lesson No: 154

Date: 17.10.2022

Before

After



Impact : Earlier during model change Oil tank and spring holding bucket not check properly as a result spring of other model get mixed

Corrective Action: Oil tank and spring holding bucket to be check thoroughly whether it is emptied and no other spring is present inside it.